

Slide 1



2010 Aircraft Airworthiness & Sustainment
(AA&S) Conference


**40-in. OMS Kevlar® COPV S/N 007 Stress
Rupture Test NDE**

NASA WSTF: Regor Saulsberry
NASA WSTF: Nate Greene
NASA JSC: Scott Forth
Jacobs/WSTF: Mark Leifeste/Tim Gallus/Tommy
Yoder/Chris Keddy
NASA LaRC: Eric Madaras/Buzz Wincheski/Philip Williams
NASA KSC: Richard Russell
NASA GRC: Jeff Eldridge




Slide 2

Overview



- Pretest Nondestructive Evaluation (NDE)
 - External/Internal Visual Inspection
 - Raman Spectroscopy
 - Laser Shearography
 - Laser Profilometry
- Real-Time NDE
 - Eddy Current
 - Acoustic Emission (AE)
 - Real-time Portable Raman Spectroscopy
- AE Application to Carbon/Epoxy (C/Ep) COPVs


Slide 3



Pretest NDE Data Review


Slide 4

***Pretest Health Assessment
OMS S/N 007***




- Visual Inspection
 - External
 - Generally clean
 - Matrix cracking, scuffs, loose fibers
 - No significant mechanical damage observed
 - Internal
 - Ripple imprints throughout
 - Debris around bottom portion of vessel
 - Minor stains and discolorations


Slide 5



Slide 6




Slide 7




Slide 8

Shearography Setup




- LTI-5100HD Shearography Camera
- COPV Pressurized with GN_2
- Test Parameters:
 - COPV biased pressure: 70 psi
 - Test pressure differential: 10 psi
 - Shear vector: 0.375 in. x, y
 - Field of view: 14.25 in.

LTI5100 HD on floor for
Band 4 Test




Laser Technology Inc.


Slide 9




Slide 10




Slide 11



Slide 12



Brief Analysis of Indications




Indications #2, #3, #4


Location: Band 3 @ 170° to 300°, 14 in. below AN-4 fitting, along the center of the equatorial circumferential Kevlar wrap

Size: #2 is 12 in. long, #3 is 9.5 in. long, and #4 is 9.0 in. long


Indications are variations in the Z axis displacement. The circumferential wrap should ideally provide uniformity around the equator. Shearography is detecting slight variations in the strength of this wrap.



Kevlar NDE Reference Standard Helped Quantify Defects




- Manufactured “damage” built into standard
- Wound at OEM
- 18 in. diameter sphere
 - Kevlar-49 fiber thick-walled (24 layers—48 plies)
- Numerous types of damage inflicted during winding process
 - Cut fibers
 - Simulated delaminations





14

Slide 15

Type of Defects in Kevlar NDE Standard



- Fiber Cuts: 1 in. and 3 in. long cuts (1 and 2 layers deep = 2-4 plies)
- Individual Delaminations: Four sizes of heat-sealed 5 mil FEP Teflon® (1 x 1 in., 1 x 2 in., 1 x 3 in., and 1 x 4 in.)
- Locations kept confidential




Typical Large Cut

Typical Delamination




15

Slide 16


Examples of Shearography Response to Kevlar NDE Standard




Z axis deformation at this anomaly is greater than adjacent areas of Kevlar wrap by 0.095 $\mu\text{m}/\text{psi}$.




Slide 17




Slide 18




Slide 19




Slide 20



Slide 21



Slide 22



Slide 23

OMS Kevlar Pretest NDE Conclusion




- With exception of the large ripples around the girth well, no indications were observed that were an issue with planned stress rupture testing
- Eddy current (EC) sensors were placed over the peak of each girth ripple and monitored during pressurization to verify the liner did not flex causing a metallic fatigue concern
 - Decrease of stand-off between the fixed composite surface and liner ripple would indicate a liner buckle and associated air pocket
 - Stand-off remained fixed during pressure cycles, signifying that the indications were not a concern

Slide 24

Eddy Current Testing to Address Buckling Question




- Three EC sensors (#1 - 3) were placed over the peak of the largest liner ripple indications, and one sensor (#4) was placed in the liner membrane region as a reference.
 - Response of Sensors #1 - 3 was in family with the membrane reference sensor, indicating ripples were not behaving as unstable "buckles" during pressurization
 - Stand-off change of 1 to 2 mils per 1000 psi was consistent with EC data obtained from other 40 in. Kevlar COPV testing




Slide 25




Slide 26




Slide 27




Slide 28




Slide 29




Slide 30




Slide 31




Slide 32




Slide 33




Slide 34






This is a view of all the AE events to date as seen from a top down view. Some event clusters appear near the equator. A few loose groupings near the poles





This is a view of all the AE events to date as seen from a top down view. Some event clusters appear near the equator. A few loose groupings near the poles

Slide 37




Slide 38





AE Summary



- There were two AE event rate increase periods that occurred during the last 7 days. The last rate increase ended in failure.
 - Over 3000 recorded events during the last 10 days
 - More than 300 very energetic events recorded during the last week
 - The rate increases were coincidental with trains of very large energy signal events.
 - The first rate increase for large energy signal events (24 to 96 hours before the end) was approximately 2/hour.
 - The second and final rate increase for large energy signal events (last 24 hours) was approximately 6/hour.
- Event energies rose to very elevated levels during the last 96 hours.
 - High energy events were > 25 times greater than energetic events in the past.
 - The loudest events occurred at the end (last 24 hours).
 - The final event, which was the loudest, was located ~45° below the equator and near the azimuth angle of 45°.

Slide 41


Portable Raman System Developed to Allow Real-time Raman Spectroscopy During Testing

WSTF/LaRC Portable Raman developed and applied in situ to Orbiter 40" vessel in stress rupture test


Tim Gallus performing bench top testing of a Raman spectrography system prior to installation in the test cell



Slide 42




Slide 43




***AE Application to Carbon COPVs
Looking to the Future***


Slide 44




Slide 45



Slide 46



Slide 47



Slide 48

Conclusion

- NDE has proven highly effective in real-time characterization of COPVs during testing
- NDE is reasonably effective in evaluating the health of COPVs, but still more work is needed to make it more quantitative